

ERECTOR NOTE:

BACK BED WITH SEALANT BEFORE THE WINDOW IS INSTALLED OR CAP SEAL AFTER THE WINDOW IS INSTALLED TO INSURE A WATERTIGHT SEAL.





| <u>NOTE:</u> THE PANNING OVERLAP ON THE WINDOW IS TOO LARGE FOR SOME WINDOW SERIES | |
|---------------------------------------------------------------------------------------------|---------------------|
| THE | PANNING OVERLAP ON |
| THE | WINDOW IS TOO LARGE |
| FOR | SOME WINDOW SERIES |

