

488 O.G. JAMB
5600 0"





634 O.G. VERT.
5600 0"

489 O.G. JAMB
5600 0"

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.



134 O.G. HEAD
5600 0"

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.

534 O.G. HORZ.
5600 0"

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.

234 O.G. SILL
5600 0"

NOTE: VERIFY ALL DIMENSIONS IN CONNECTION WITH THIS DRAWING TO BE COMPLETELY CORRECT AND TO REFLECT THE FIELD OF VIEW OF THE WINDOW.